

FIG. 1




FIG. 2




FIG. 3




FIG. 4





FIG. 5






FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18

EXTENSION NUMBER	COMMUNICATION TERMINAL ADDRESS
1234	133. 144. 6. 10
3446	133. 144. 6. 9
5678	133. 144. 5. 1
...	...
8769	133. 144. 5. 6

FIG. 19





FIG. 20



20241010 09:23:00

FIG. 21

501	509	510	511
COMMUNICATION HEADER	IDENTIFIER OF CONNECTED TERMINAL DETERMINATION NOTICE COMMAND	RESULT	COMMUNICATION TERMINAL ADDRESS

FIG. 22

337	311	312
NAME	EXTENSION NUMBER	COMMUNICATION TERMINAL ADDRESS
TANAKA	1234	133. 144. 6. 10
SUZUKI	3446	133. 144. 6. 9
SATOH	5678	133. 144. 5. 1
AZUMA	8769	133. 144. 5. 6

FIG. 23

